IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No. : 7,485,089 B2 Confirmation No. : 8236

Inventor : Lilip Lau et al. Issued : February 3, 2009

Appl. No. : 10/656,722

Art Unit : 3735

Examiner : John P. Lacyk

Title : CARDIAC HARNESS

Docket No.: : PARCR 66117

Customer No. : 24201

Certificate of Corrections Branch Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION

Dear Sir:

The above-identified patent application file has been found to have the errors set forth in the enclosed Certificate of Correction. It is noted that the one applicant error that appear in the above-identified patent is of a clerical, typographical or minor nature or character, as more fully described below.

The errors are verifiable in the patent application file as follows:

ERRORS

VERIFICATION

Title Page, (75) Inventors, delete "Sieu Dong" and insert -- Sieu Duong--.

PTO error. See Updated Filing Receipt dated 4/09/04.

Column 5, line 67, after "is" delete "accurate" and insert -- arcuate--.

Applicant's error.

Correction thereof does not involve such changes in the patent as would constitute new matter or would require re-examination. It is requested that a Certificate of Correction be issued and returned to us. If any fees are needed, please charge Deposit Account No. 06-2425.

Attached hereto is Form PTO/SB/44 which is suitable for printing.

Date: April 21, 2009 Respectfully submitted,

FULWIDER PATTON LLP

By: /michael j. moffatt/ Michael J. Moffatt Registration No. 39,304

MJM:he FULWIDER PATTON LLP Howard Hughes Center 6060 Center Drive, Tenth Floor Los Angeles, CA 90045 Telephone: (310) 824-5555 Facsimile: (310) 824-9696

Customer No. 24201

338126.1

U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(also Form PTO 1050)

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION				
PATENT NO.	: 7,485,089 B2			Page <u>1</u> of <u>1</u>
APPLICATION NO. : 10/656,722				
ISSUE DATE	: February 3, 200	9		·
INVENTOR(S)	: Lilip Lau et al.			
It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:				
Title Page, (75) Inventors, delete "Sieu Dong" and insert Sieu Duong				
Column 5, line 67, after "is" delete "accurate" and insertarcuate				
	•			
·				
		•		
	•			

338128.1

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Michael J. Moffat, Esq. Fulwider Patton LLP 6060 Center Drive, 10th Floor Los Angeles, CA 90045

This collection of information is required by 37 CFR 1.322, 1.323 and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department. of Commerce, PO Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450 Alexandria, VA 22313-1450.